

FIG. 3a




FIG. 3b

	WL	BL	SL
Program	Vt/Cnd	Cnd	12V
Erase	14V	Cnd	Cnd
Read	Vcc	1V	Cnd

FIG. 4